

TOP SECRET OXCART

ACCIDENT INVESTIGATION BOARD FINDINGS


- ▶ PRIMARY CAUSE: **UNDETERMINED**
- ▶ MOST PROBABLE CAUSE: **CATASTROPHIC FAILURE OF RIGHT ENGINE**
- ▶ RECOMMENDATIONS: **NONE**

25 YEAR RE-REVIEW

TOP SECRET OXCART

BEST COPY
Available

Approved For Release 2010/06/08 : CIA-RDP71B00590R000200020089-6



Approved For Release 2010/06/08 : CIA-RDP71B00590R000200020089-6

TOP SECRET OXCART

SEARCH AND RESCUE EFFORT

U.S NAVY SHIP
USS SERRANO
ON SCENE 5 JUNE 1968 1200Z

TOTAL SEARCH SORTIES
91
TOTAL HOURS FLOWN
869.35

LAST CONTACT
4 JUNE 1968 0542 482
SEARCH AREA WEATHERED
CLEAR / 70°F 75°F
SEA STATE 1

168.100.100.2